Treadmill Vibration Isolation System (TVIS) In-Flight Maintenance (IFM) Hammering Qualify



| Data Description | |
|------------------|----------------|
| Sensor | |
| Location | Deck of US LAB |
| Inc/Flight | |
| Plot Type | |

Notes:

The Principal Investigator Microgravity Services (PIMS) database has a 37 minute 11 second video (2004_03_09_tvis_ifm.wmv) that shows the two Increment 8 crew members working together on a Treadmill Vibration Isolation System (TVIS) In-Flight Maintenance (IFM) task. The database also contains a spreadsheet excerpt of the PIMS telescience support center console logbook (pimslog_2004_03_08_14_15_51excerpt.xls) for part of a day, which details some of the action as it was observed on live module video downlink. In order to reseat a bearing, some hammering was required for this IFM while the flywheel was held on the deck of the US Lab.






| Glenn | Research | Center |
|-------|----------|--------|

| Regime: | Vibratory |
|-----------|---|
| Category: | Crew |
| Source: | Treadmill Vibration Isolation System (TVIS) In-Flight Maintenance (IFM) Hammering |

Treadmill Vibration Isolation System (TVIS) In-Flight Maintenance (IFM) Hammering Quantify



| 16 | |
|----|----|
| N | SA |
| | |

Microgravity Science Division

Glenn Research Center

| Data Description | |
|------------------|----------------|
| Sensor | |
| Location | Deck of US LAB |
| Inc/Flight | |
| Plot Type | |

Notes:

Comparing some acceleration magnitude statistics derived from measurements collected by the SAMS sensor heads located overhead toward the forward end of the US Lab,

| SAMS Sensor | Accleration Vector Magnitude (mg) | |
|----------------|--|---|
| | Maximum During 20- Minute Span* | 95 th %-ile For Entire Day |
| 121f02 | 3.43 | 0.88 |
| 121f03 | 11.36 | 2.40 |
| 121f04 | 42.88 | 2.45 |
| 121f05 | 2.37 | 0.68 |

it is evident that this deck-based hammering transmitted vibrations quite well to the SAMS sensor head locations.

| Regime: | Vibratory |
|-----------|---|
| Category: | Crew |
| Source: | Treadmill Vibration Isolation System (TVIS) In-Flight Maintenance (IFM) Hammering |

^{*} span started at GMT 09-Mar-2004, 14:50:03.