

1. INTRODUCTION

Referring to roadmap spectrogram and not long after GMT 16:00..."This looks to coincide with a reboot that we performed that morning where power was cut to our instrument for ~5 minutes. The AAA fans on the back of our lockers as well as flight computer fan all go OFF during that time."

2. QUALIFY


The Qualify section goes here.

3. QUANTIFY

The Quantify section goes here.

4. CONCLUSION

The conclusion section goes here.



VIBRATORY

MODIFIED SEPTEMBER 18, 2024




Fig. 2: SAMS Sensor 121f04 in LAB1P2, Below 200 Hz, ~8-Hour Spectrogram Starting at GMT 2024-09-06/16:00.